



BM16




Adjustable Gib Strips

These are fitted to the column and the tables in both forward/reverse and lateral movement systems. Also features locking bolts when the table needs to be kept securely in one position.




Gas Springs

Gas springs provide smooth movement and help the headstock return to position.



Cast Iron Clamp

With 3 sets of holes in the table and slots on the clamp base, a wide range of positions can be set to accommodate different widths of workpiece.




Sliding Table

A rack and pinion system provides easy lateral movement and features machined dovetail slides for accuracy.



Easy Access

The chuck is easily accessible from the side of the headstock making changing the bits a quick and simple procedure.



Precision Adjustment

Front to back and side to side movement are controlled with two separate handwheels, precision engineered for optimum accuracy.